

Almeda and South Obenchain Fire Debris Residential Homeowner Self-Cleanup Guide

Certified testing firm must be used to collect samples of the waste, have it tested, and provide a written report of the testing results to the Landfill or Transfer Station.

Building/Structure Debris ONLY: Asbestos Survey/Testing required. - Fire materials containing Ash or Soil: Testing for TCLP metals, TPH and Asbestos required.

Fire debris, ash and soil will not be accepted at Dry Creek Landfill or Transfer Station without appropriate documentation/testing from a certified firm.

Vehicles, large pieces of metal, appliances, propane or fuel tanks, or any hazardous materials must be removed from the waste and disposed of in accordance with applicable laws.

TEST RESULTS

(a) NO asbestos and (b) TCLP (metals) and TPH (petroleum) levels BELOW hazardous levels

CLEAN UP

PROFESSIONAL REMEDIATION FIRM SHOULD BE UTILIZED GIVEN DANGERS OF ASH AND OTHER FIRE DEBRIS AND FIRE SITE CLEANUP RISKS. **Clean-up by owner NOT recommended or endorsed.** If owner continues with cleanup, appropriate personal protective gear should be worn plus appropriate fire debris handling procedures should be followed.

HAULING

Property owner may:

1. In Phoenix or Medford contact Rogue Disposal (541.779.4161), in Talent or Ashland contact Recology Ashland (541.482.1471) or in connection with the Obenchain fire contact Southern Oregon Sanitation (541.826.5691) to obtain an appropriate container and hauling services.
2. Rent dump truck and deliver the waste to Dry Creek Landfill. An account with Dry Creek Landfill needs to be pre-established.
3. Rent trailer with less than 8-yard capacity and deliver to Rogue Transfer & Recycling White City Transfer Station or deliver to another Jackson County Transfer Station subject to their requirements.

TRANSPORTATION/DISPOSAL

1. **Landfill:** Material must be wetted down prior to transportation and/or wrapped in 6 ml plastic. Ash wetted down in roll off containers must have a liner of at least 6 ml plastic to minimize dispersion through transportation and disposal.

2. **Transfer Station:** Must be wrapped ("burrito") wrapped least 6 ml plastic.

The testing results must accompany the waste brought to a Transfer Station. Test Results must be sent to Dry Creek Landfill prior to the waste being delivered directly to the landfill. We recommend obtaining a pre-acceptance letter from the landfill to present at the scale house.

TEST RESULTS

(a) CONTAINS Asbestos but (b) TCLP (metals) and TPH (petroleum) levels BELOW hazardous levels

CLEANUP

PROFESSIONAL REMEDIATION FIRM SHOULD BE UTILIZED GIVEN PRESENCE OF ASBESTOS AND FIRE SITE CLEANUP RISKS. **Cleanup by owner NOT recommended or endorsed.** If owner continues with cleanup, appropriate personal protective gear should be worn plus appropriate asbestos and fire debris handling procedures should be followed.

HAULING

Property owner may:

1. In Phoenix or Medford contact Rogue Disposal (541.779.4161), in Talent or Ashland contact Recology Ashland (541.482.1471) or in connection with the Obenchain fire contact Southern Oregon Sanitation (541.826.5691) to obtain an appropriate container and hauling services.
2. Rent dump truck and deliver the waste to Dry Creek Landfill. An account with Dry Creek Landfill needs to be pre-established.

TRANSPORTATION/DISPOSAL

1. Ash and soil that tested positive for asbestos containing materials must be wetted down and wrapped in two layers of 6 ml plastic. 6 ml bags should be wrapped with a 10 ml scrim reinforced plastic liner (burrito style) if material can puncture or tear the 6 mil bags. Each layer must be sealed separately.
2. An ASN 4 form must be completed and accompany the material for transport and disposal.

The testing results must be sent to Dry Creek Landfill prior to the waste being delivered to the landfill. We recommend obtaining a pre-acceptance letter from the landfill to present at the scale house.

Asbestos containing material is NOT accepted at Transfer Stations.

TEST RESULTS

HAZARDOUS levels of TCLP (metals) or TPH (petroleum) (regardless of Asbestos results)

Site contains HAZARDOUS WASTE – Cleanup requires professional Remediation Firm to ensure appropriate cleanup and disposal of waste. Hazardous Waste cannot be accepted at Dry Creek Landfill or any Transfer Station from owner cleanup.



drycreeklandfill.com

Dry Creek Landfill, Inc. has published these guidelines for informational purposes only.

Due to the SIGNIFICANT HAZARDS POSED BY EXPOSURE TO FIRE DEBRIS (including Ash & Soils), Dry Creek Landfill strongly encourages homeowners NOT to attempt fire damage debris cleanup themselves, but instead hire qualified professionals.

Any homeowner conducting a cleanup of fire debris does so at their own risk.

All applicable Transfer Station and Landfill disposal requirements apply regardless, and all activities need to be conducted in compliance with applicable laws. Individual Transfer Stations may have additional rules or limitations.

For questions or assistance, call Dry Creek Landfill Customer Service at 541.779.4161.

10-13-2020

*** IMPORTANT INFORMATION ***

For a self-cleanup, under Jackson County laws, only the property owner or a franchised hauler can deliver the waste to Dry Creek Landfill or Transfer Stations. A 3rd party (non-franchised hauler) may not be used. WASTE IMPROPERLY WRAPPED OR LACKING APPROPRIATE DOCUMENTATION WILL NOT BE ACCEPTED FOR HAULING OR DISPOSAL. Homeowners should check with their local jurisdiction prior to any self-cleanup to ensure there are not local regulations relating to the cleanup or subsequent rebuilding. Self-cleanup may impact insurance reimbursement and the ability to secure funding for new construction.